CONDITION REPORT - ELECTRIC

| Manufacturer | Model | Year | Serial Number | | |
|-------------------------------------------------------|----------------|------|---------------------------|----------------|--|
| YALE MANUFACTURER | MPE080-VG | 2010 | B890N02783H | | |
| | | 2010 | 2000.027.0011 | | |
| Mast | N/A | | Hours | 1431 | |
| Mast Height Lowered | | | Voltage | 24 Volt | |
| Mast Height Raised | | | Attachment | None | |
| Hydraulic Control Valve | | | Directional Control | Lever | |
| Capacity | | | Tires | Cushion | |
| | | | | | |
| Mast Condition | | | Steering Pump Condition | Not applicable | |
| Mast Comments | | | Steering Pump Comments | | |
| Lift Cylinder Condition | | | Hydraulic Pump Condition | | |
| Lift Cylinder Comments | | | Hydraulic Pump Comments | | |
| Tilt Cylinder Condition | Not applicable | | Hydraulic Motor Condition | | |
| Tilt Cylinder Comments | | | Hydraulic Motor Comments | | |
| Carriage Condition | | | Control System Condition | | |
| Carriage Comments | | | Control System Comments | | |
| Load Backrest Condition | | | | | |
| Load Backrest Comments | | | Drive Motor Condition | | |
| Forks Condition | | | Drive Motor Comments | | |
| Forks Comments | | | Differential Condition | | |
| | | | Differential Comments | | |
| Overhead Guard Condition | Not applicable | | Drive Tires % Remaining | 30 | |
| Overhead Guard Comments | | | Drive Tires Condition | | |
| | | | Steer Tires % Remaining | | |
| Seat Condition | Not applicable | | Steer Tires Condition | Not applicable | |
| Seat Comments | | | Steer Axle Condition | Not applicable | |
| | | | Steer Axle Comments | | |
| General Appearance Condition | Poor | | Brakes Condition | | |
| General Appearance Comments | | | Brakes Comments | | |
| | | | | | |
| General Comments | | | Battery Present | Yes | |
| Pivot rod has play. Right side caster wheel is broken | | | Charger Present | Yes | |
| | | | | | |
| | | | Electrical Condition | | |
| | | | Electrical Comments | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Inspector Company NameYale/ChaseInspection Date9/19/2018 3:31:12 PMInspector Namerafael











