CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number		
YALE MANUFACTURER	ERC050VG	2012	A968N07085K		
Mast			Hours	8117	
Mast Height Lowered	ok		Voltage	36 Volt	
Mast Height Raised	ok		Attachment	None	
Hydraulic Control Valve	3-Function		Directional Control	Lever	
Capacity	4850 lbs		Tires	Non-Marking	
			0		
Mast Condition	Needs chains/hoses		Steering Pump Condition		
Mast Comments	Lift Chains stretched		Steering Pump Comments		
Lift Cylinder Condition	Bent		Hydraulic Pump Condition		
Lift Cylinder Comments	gouge on the cylinder		Hydraulic Pump Comments		
Tilt Cylinder Condition			Hydraulic Motor Condition		
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition			Control System Condition		
Carriage Comments			Control System Comments		
Load Backrest Condition					
Load Backrest Comments			Drive Motor Condition		
Forks Condition	Heels worn		Drive Motor Comments		
Forks Comments	dragged marks		Differential Condition		
			Differential Comments		
Overhead Guard Condition	Damaged		Drive Tires % Remaining	90%	
Overhead Guard Comments	Impact damage RR leg		Drive Tires Condition	Chunked	
			Steer Tires % Remaining	90%	
Seat Condition	Damaged		Steer Tires Condition	Chunked	
Seat Comments	there puncher holes		Steer Axle Condition		
			Steer Axle Comments		
General Appearance Condition	Fair		Brakes Condition	Grabs	
General Appearance Comments	Impact damage		Brakes Comments	Worn Out	
• •	· -				
General Comments		Battery Present	Yes		
there signs that the right rear over head guard was hit and pushed the tail lamp over missing hardware on the hood		Charger Present	Yes		
latch assembly.some gouging on the middle of the mast , facing out.loose mounting brackets on the work lamps		Florida I Octobri			
			Electrical Condition		
			Electrical Comments		

Inspector Company Name	Yale/Chase	Inspection Date	1/25/2018 11:19:16 AM
Inspector Name	csanchez		



















