

CONDITION REPORT - INTERNAL COMBUSTION


	2013	F187V24137L		
1				
Most Height Lowered	FL (Triplex)	Hours	3410	
Mast Height Lowered		Fuel	LP Gas	
Mast Height Raised 187.8		Attachment	Side Shifter	
Hydraulic Control Valve 3-Function	n	Directional Control	Lever	
Capacity 6000		Tires	Cushion	
Mast Condition		Engine	Mazda	
Mast Comments		Engine Inspected Condition	Mazda	
		Engine Inspected Condition		
Lift Cylinder Condition		Engine Inspected Comments		
Lift Cylinder Comments		Radiator Condition		
Tilt Cylinder Condition		Radiator Comments		
Tilt Cylinder Comments		Transmission/MDU Condition		
Carriage Condition		Transmission/MDU Comments		
Carriage Comments		0, , , , , , , , , , , , , , , , , , ,		
Load Backrest Condition		Steering Pump Condition		
Load Backrest Comments		Steering Pump Comments		
Forks Condition		Hydraulic Pump Condition		
Forks Comments		Hydraulic Pump Comments		
		Hydraulic Motor Condition		
Overhead Guard Condition		Hydraulic Motor Comments		
Overhead Guard Comments		Control System Condition		
		Control System Comments		
Seat Condition Damaged				
Seat Comments TORN Co	DRNERS	Differential Condition		
		Differential Comments		
General Appearance Condition		Drive Tires % Remaining	75	
General Appearance Comments		Drive Tires Condition		
		Steer Tires % Remaining	75	
General Comments		Steer Tires Condition		
		Steer Axle Condition		
		Steer Axle Comments		
		Brakes Condition		
		Brakes Comments		
		Electrical Condition		
		Electrical Comments		

Inspector Company Name MH EQUIPMENT Inspection Date 9/26/2018 7:21:23 AM Inspector Name Jmarzian











Powershift 1 Speed Transmission

Instructions

Check Operating



