## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number		
HYSTER COMPANY	B60ZAC	2014	C230N01756M		
Mast	N/A		Hours	2270	
Mast Height Lowered			Voltage	24 Volt	
Mast Height Raised			Attachment	None	
Hydraulic Control Valve			Directional Control		
Capacity			Tires		
Mast Condition	Not applicable		Steering Pump Condition		
Mast Comments			Steering Pump Comments		
Lift Cylinder Condition	Not applicable		Hydraulic Pump Condition		
Lift Cylinder Comments			Hydraulic Pump Comments		
Tilt Cylinder Condition	Not applicable		Hydraulic Motor Condition		
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition	Not applicable		Control System Condition		
Carriage Comments			Control System Comments		
Load Backrest Condition	Not applicable				
Load Backrest Comments			Drive Motor Condition		
Forks Condition	Not applicable		Drive Motor Comments		
Forks Comments			Differential Condition		
			Differential Comments		
Overhead Guard Condition	Not applicable		Drive Tires % Remaining		
Overhead Guard Comments			Drive Tires Condition		
			Steer Tires % Remaining		
Seat Condition			Steer Tires Condition		
Seat Comments			Steer Axle Condition		
			Steer Axle Comments		
General Appearance Condition			Brakes Condition		
General Appearance Comments			Brakes Comments		
General Comments			Battery Present	Yes	
some body damage			Charger Present	Yes	
			Electrical Condition		
			Electrical Comments		

Inspector Company Name	Briggs Equipment	Inspection Date	12/5/2018 12:21:41 PM
Inspector Name	Icaldwell		













