## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model E45XN	Year 2013	Serial Number A268N10061L		
HYSTER COMPANY					
Mast	3 Stage FFL (Triplex)		Hours	3559	
Mast Height Lowered			Voltage	48 Volt	
Mast Height Raised	189		Attachment	Side Shifter	
Hydraulic Control Valve	3-Function		Directional Control	Lever	
Capacity	4500		Tires	Cushion	
Mast Condition			Steering Pump Condition		
Mast Comments			Steering Pump Comments		
Lift Cylinder Condition			Hydraulic Pump Condition		
Lift Cylinder Comments			Hydraulic Pump Comments		
Tilt Cylinder Condition			Hydraulic Motor Condition		
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition			Control System Condition		
Carriage Comments			Control System Comments		
Load Backrest Condition			•		
Load Backrest Comments			Drive Motor Condition		
Forks Condition			Drive Motor Comments		
Forks Comments			Differential Condition		
			Differential Comments		
Overhead Guard Condition			Drive Tires % Remaining	70	
Overhead Guard Comments			Drive Tires Condition		
			Steer Tires % Remaining	70	
Seat Condition			Steer Tires Condition		
Seat Comments			Steer Axle Condition		
			Steer Axle Comments		
General Appearance Condition	Good		Brakes Condition		
General Appearance Comments			Brakes Comments		
0 10			B B	<b>V</b>	
General Comments			Battery Present	Yes	
			Charger Present	Yes	
			Florida I Occupio		
			Electrical Condition		
			Electrical Comments		

Inspector Company Name Briggs Equipment Inspection Date 12/5/2018 4:12:44 PM Inspector Name jdelagarza







