## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number	
IYSTER COMPANY	E35HSD2	2013	B219N02045L	
Mast			Hours	7471
Mast Height Lowered	84		Voltage	36 Volt
Mast Height Raised	241		Attachment	
Hydraulic Control Valve	3-Function		Directional Control	Lever
Capacity			Tires	
Mast Condition			Steering Pump Condition	
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition			Control System Condition	
Carriage Comments			Control System Comments	
Load Backrest Condition			Control System Comments	
Load Backrest Comments			Drive Motor Condition	
			Drive Motor Condition Drive Motor Comments	
Forks Condition				
Forks Comments			Differential Condition	
			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	90
Overhead Guard Comments			Drive Tires Condition	
			Steer Tires % Remaining	90
Seat Condition			Steer Tires Condition	
Seat Comments			Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition			Brakes Condition	
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
			Charger Present	Yes
			Electrical Condition	
			Electrical Comments	
nspector Company Name	PAPE MATERIAL HANDLING		Inspection Date	12/12/2017 6:37:42 PM
senactor Namo	Dorick Guzman			

Derick Guzman

Inspector Name



