

# CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number
HYSTER COMPANY	E50XN	2013	A268N10265L

Mast	3 Stage FFL (Triplex)	Hours	6336
Mast Height Lowered		Voltage	36 Volt
Mast Height Raised	189	Attachment	Side Shifter
Hydraulic Control Valve	3-Function	Directional Control	Lever
Capacity		Tires	Cushion

Mast Condition	Steering Pump Condition
Mast Comments	Steering Pump Comments
Lift Cylinder Condition	Hydraulic Pump Condition
Lift Cylinder Comments	Hydraulic Pump Comments
Tilt Cylinder Condition	Hydraulic Motor Condition
Tilt Cylinder Comments	Hydraulic Motor Comments
Carriage Condition	Control System Condition
Carriage Comments	Control System Comments

Load Backrest Condition	Drive Motor Condition
Load Backrest Comments	Drive Motor Comments
Forks Condition	Differential Condition
Forks Comments	Differential Comments

Overhead Guard Condition	Drive Tires % Remaining	70
Overhead Guard Comments	Drive Tires Condition	

Seat Condition	Steer Tires % Remaining	60
Seat Comments	Steer Tires Condition	
	Steer Axle Condition	
	Steer Axle Comments	

General Appearance Condition	Brakes Condition
General Appearance Comments	Brakes Comments

General Comments	Battery Present	Yes
	Charger Present	Yes

Battery very weak if not dead

Electrical Condition
Electrical Comments

Inspector Company Name	Pape	Inspection Date	12/17/2018 2:59:58 PM
Inspector Name	bemerson		

(\* Legend: =Checked OK)







