CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number	
HYSTER COMPANY	R30XM3	2013	H118N01717L	
Mast			Hours	4217
Mast Height Lowered			Voltage	24 Volt
Mast Height Raised	188		Attachment	None
Hydraulic Control Valve			Directional Control	Lever
Capacity	2500		Tires	Cushion
Mast Condition			Steering Pump Condition	
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition	Not applicable		Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition	Not applicable		Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition	Not applicable		Control System Condition	
Carriage Comments	Not applicable		Control System Comments	
Load Backrest Condition	Not applicable		Control System Comments	
	Not applicable		Drive Motor Condition	
Load Backrest Comments			Drive Motor Condition	
Forks Condition			Drive Motor Comments	
Forks Comments			Differential Condition	
			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	
Overhead Guard Comments			Drive Tires Condition	
			Steer Tires % Remaining	
Seat Condition	Not applicable		Steer Tires Condition	
Seat Comments			Steer Axle Condition	Not applicable
			Steer Axle Comments	
General Appearance Condition	Good		Brakes Condition	Not applicable
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	No
			Charger Present	Yes
			Electrical Condition	
			Electrical Comments	
Inspector Company Name	Briggs		Inspection Date	8/28/2018 11:36:18 PM
Inspector Name	idologorzo			0,20,20.0

(* Legend: =Checked OK)

jdelagarza

Inspector Name









